General Environmental Incident Summary

Incident: 3234 Date/Time Notice: 3/6/2014 1030 DEM Incident No:

Responsible Party: Enduro Operating LLC

Date Incident: 3/6/2014 Time Incident: 1030 Duration:

County: Burke Twp: 164 Rng: 90 Sec: 32 Qtr: SE SE

Lat: 48.98225 **Long:** -102.37250 **Method:** Calculated

Location Description: Wilson 44-32 H NDIC File #14885

Submitted By: Scott Hunskor Affiliation: Production Supervisor

Address: PO Box 444

City: Westhope State: ND Zip: 58793

Received By:

Contact Person: Scott Hunskor

PO Box 444

Westhope, ND 58793

Distance Nearest Occupied Building: 1 Miles Release Contained: Yes

Type of Incident: Valve Leake

Description of Released Contaminant: Production Water

Volume Spilled: 40.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Valve on water tank leaked

Risk Evaluation:

None

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in well, order pump truck, load up spilled water in dike, haul to SWD, empty tank and replace valve

.

Wastes Disposal Location: SWD

Agencies Involved:

Updates

Date: 3/6/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Volume:

Notes:

Release, due to valve leak on the produced water tank, remained on location apparently within the diking, according to the report. Report forwarded to NDIC for oversight.